




Why choose it?

HOT HUMIDIFIER
2nd patent system




Antigeysersystem

Problem of traditional devices:

"Geyser Effect": uncontrolled spillage of boiling liquid from the air exit, in liquid and steam form. This effect is very dangerous, but we have the solution!

Our solution:

Conveyance structure (1) divides thermally the steam exit in order to avoid the risk of being burned and helps to redirect the steam and hot water in the tank. **Discharge openings (2)** let the boiling water and hot steam remain inside the appliance during "Geyser Effect". the shape of **collector (3)** allows to hold eventual essence drops introduced in the boiler by mistake.



elettroplastica
since 1963



Elettroplastica S.p.A.

via Del Commercio, 1 - 25039 Travagliato (BS) - Italy
+39 030 25 83 990 - www.elettroplastica.com